



Quotations are invited for the repair/ maintenance work of Columns and Stairs cases at KG/ Boys wing. Details are as under.

Si #	Description	Area (m2)	Concrete Condition	Re-Bars Condition
1	Stair-case 1			
	Stair	13.80	crack & loose	90% Good
	Walls	14.15	crack & loose	90% Good
2	Stair-case 2			
	Stair	7.50	crack & loose	90% Good
	Walls	4.15	crack & loose	90% Good
3	Stair-case 3			
	Stair	27.87	crack & loose	85% Good
4	Column 1	0.73	crack & loose	90% Good
5	Column 2	0.58	crack & loose	90% Good
6	Column 3	0.70	crack & loose	90% Good
7	Column 4	1.12	crack & loose	90% Good
8	Column 5	0.84	crack & loose	90% Good
9	Column 6	1.12	crack & loose	90% Good
10	Column 7	0.98	crack & loose	90% Good
11	Column 8	0.84	crack & loose	90% Good
12	Column 9	0.66	crack & loose	90% Good
13	Column 10	1.26	crack & loose	90% Good
14	Column 11	0.84	crack & loose	90% Good
15	Column 12	0.56	crack & loose	90% Good
16	Column 13	1.12	crack & loose	90% Good
17	Column 14	1.40	crack & loose	90% Good
18	Column 15	0.78	crack & loose	90% Good
19	Column 16	0.78	crack & loose	90% Good
20	Column 17	1.82	crack & loose	90% Good
21	Column 18	1.26	crack & loose	90% Good
22	Column 19	1.68	crack & loose	90% Good
23	Column 20	1.68	crack & loose	90% Good
24	Column 21	1.40	crack & loose	90% Good
25	Column 22	0.65	crack & loose	90% Good
26	Column 23	0.78	crack & loose	90% Good
27	Column 24	1.40	crack & loose	90% Good
28	Column 25	0.98	crack & loose	90% Good
29	Column 26	1.12	crack & loose	90% Good
30	Column 27	0.33	crack & loose	90% Good
31	Column 28	0.59	crack & loose	90% Good
32	Column 29	1.12	crack & loose	90% Good
33	Column 30	0.84	crack & loose	90% Good
34	Column 31	1.40	crack & loose	90% Good
35	Column 32	0.84	crack & loose	90% Good
36	Column 33	1.40	crack & loose	90% Good
37	Column 34	2.10	crack & loose	90% Good
Total Area:		103.17		